Attachment

_____ 25X1

CONFIDENTIAL

<u>ಸರ್ವಹ್ಯದೆ 16 ಗಿನರ, 311 3</u>

- A. Lenir Plant and PW Camp.
- D. Haphtla Basa.
- C. Aircraft plant.
- D. Ball bearing plant.
- E. Airfield.
- P. Naphtha Basa.
- C. Oil area.

Legend to Sketch 2.

- 1. Entrance and guardhouse.
- 2. Shipping hall with ramp 200 x 20 meters.
- Kitchen, mess hall and storage facilities, called "stolovaya", and measuring 100 x 20 meters.
- 4. "echanical department, 50 x 10 meters, equipped with 20 German automatic lather and about 30 new German milling, boring, and planing machines.
- lathes and about 30 new German milling, boring, and planing machines.

 5. Wire mill, 50 x 10 meters, equipped with about 20 gas-burning annealing furnaces.
- 6. Forge and small foundry, 50 x 30 neters, equipped with a gas-burning furnace, two old steam hammers of three and five tons, and several presses and punching machines in addition to four or five small gas-burning annealing furnaces.
- 7. Rail spikes shop, 50 x 10 meters, equipped with about five shears and three old German nail presses with gas-burning annealing furnaces.
- 8. Electrical department (sic), 10 x 5 meters. The plant had no power station of its own.
- 9. Nail shop, 50 x 10 meters, equipped with 20 automatic German nail presses each of which had one gas-burning annealing furnace. Netf of the machinery was now.
- 10. Water tower, 10 meters in diameter and 25 meters high.
- 11. Three story administration building.
- 12. PW Caup No 7238/10.
- 12a.Guardhouse.
- 13. Watch towers.

The gas needed for the furnaces was directed to the plant through gas pipes about 150 cm underground and 20 cm in diameter.

CONFIDENTIAL

25X1